

Industrial Audit

Suzuki Motors, Lagos, Nigeria

EDESSA was retained by the Boulos Group to conduct an industrial audit of their motorcycle assembly plant and warehouse located in Lagos in order to optimize the design of a new facility to be located outside the city.

The industrial audit consisted of reviewing the product handling schemes required for the assembly of the motorcycles and tricycles.

The audit started with the administrative and logistic aspects and continued with the production and support activities.

